

WO 2004/039591

PCT/DE2003/03529

List of Reference Symbols

01	Rotating body, cylinder, roller, forme cylinder, transfer cylinder
02	Barrel
03	Dressing, printing forme, rubber printing blanket
04	Profiled body
05	-
06	Bracing channel
07	Shell face
08	Leg
09	Leg
10	-
11	Opening
12	Wall
13	Wall
14	Bottom
15	-
16	Leading end
17	Trailing end
18	Front edge
19	Rear edge
20	-
21	Groove
22	Holding means, strip, lever
23	First end
24	Second end
25	-
26	Spring

WO 2004/039591

PCT/DE2003/03529

27	Actuating means, hose
28	Base body
29	Surface (28)
30	-
31	Groove
32	Welding zone
33	Protective coating (02)
34	Front face
35	-
36	Covering
37	Flow channel, coolant channel
38	Exterior body
39	Front side
40	-
41	Zone
42	Zone
43	Groove
44	Radial bore
45	-
46	Strip
a	Protrusion (04)
B	Width (21)
D	Thickness (22)
P	Production direction (01)
S	Slit width (11)
t	Depth (06)
T	Tangent line
W31	Width (31)

WO 2004/039591

PCT/DE2003/03529

$\alpha$  Opening angle

$\beta$  Opening angle